


Handling Precautions


Soldering

1. General design

Recommendation Land Pattern
(Component side)



2. General cautions for soldering



For soldering, please perform a temperature pattern of the right note for reference.


Please do not perform heating more than 260 degrees Celsius 10 seconds.

I received the internal joining, but I melt, and such as a short circuit, opening, a gap of a case may occur.

This part is the lead-free correspondence kind that I received.

3. Taping

Tape size (Tape material: Plastic)



Wrapping quantity

Type	Wrapping quantity
Taping	1,000pics / reel