


Handling Precautions


Soldering

1. General design

Recommendation Land Pattern
(Component side)




2. General cautions for soldering



For soldering, please refer to the soldering curves.
This part is lead-free soldering.

3. Taping

Tape size (Tape material: Plastic)



Wrapping quantity

Type	Wrapping quantity
Taping	1,000pics / reel